Steps:
1) Attach base plate to straight end of post, using bolt.
2) Attach mounting plate to curved end of post, using bolt.
   NOTE: Plate must rotate to left and right before installing clamshell.
3) Attach clamshell to mounting plate, using acorn nuts.
   See Clamshell Attachment detail.
4) Insert iPad in clamshell, then route cords through holes. See
   Cord Management for iPad detail.
5) Attach graphics to post using A10 clamps. See A10 Clamp detail.

Clamshell Attachment

Cord Management For iPad

Lock   Lock

Clamshell

iPad

Cord Access

Attach iPad cord to supplied USB extension cord. Feed USB cord through top hole of post, then out bottom hole of post. connect to power.

Acorn Nut   Clamshell

Mounting Plate

Cord from iPad

Post

Graphic

Graphic

Base Plate

USB Extension Cord

A10 Clamp

Connector

1) Slide connector of clamp into extrusion groove.
2) Tighten set screw when A10 is in desired location.
3) Insert graphic into clamp.
4) Tighten knob on clamp to secure graphic in place.

Set Screw

A10 Clamp

Knob

Rotate clamshell to turn iPad from portrait to landscape orientation.

Completed Assembly

Optional Cover for Home Button

Foam Lining Removed   Home Button Shield

1) Remove foam lining from inside bottom of clamshell.
2) Attach Home Button Shield with double-sided tape to inside of clamshell, keeping top of shield flush with clamshell opening.
NOTE: This is a permanent fix and can't be easily removed.

SETUP INSTRUCTIONS

If you would like to tell us about your experience with our setup instructions please email us at **info@classicexhibits.com**

© 2023

General Setup Instructions

- Read entire setup instruction manual prior to unpacking parts and pieces.

- The setup instructions are created specifically for this configuration.

- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.

- Keep exhibit components away from heat and prolonged sun exposure. **Heat and UV exposure will warp and fade components.**

- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all set screws and locks during disassembly.


Hex Tool - Essential for Assembly

Part Identification - Numbering

Spline Connection

Base Plate & Extrusion Connection

Extrusion & Lock Connection

Engaged Lock

WARNING

DO NOT USE POWER TOOLS

LADDERS OR LIFTS MAY BE REQUIRED

ALL CONNECTIONS MUST BE TIGHTLY SECURED